








Work Order ID 51760

September 02, 2009 1:42:27 PM




Page 1


Item ID: D2230-3 Accept  Setup Start 
Revision ID: F Stop 
Item Name: Lug
Start Date: 09/02/09 Start Qty: 4.00  Cust Item ID:
Required Date: 09/09/09 Req'd Qty: 4.00  Customer:
Reference: Return 2009 / RA109088

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start 
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop 

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	----------------	--------------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D2230	Rev F

100	QC5- Inspect part completeness to step on W/O	0.00							
									
QC	Memo	0.00							
Quality Control	Original B47110. Parts in bag, and good condition.								


110	Identify as per dwg & Stock Location: <u>S1476</u>	0.00							
									
Packaging	Memo	0.00							
Packaging	Return to stock with the new batch #. Location: _____								

120	QC21- Final Inspection - Work Order Release	0.00							
									
QC	Memo	0.00							
Quality Control									

From: Return 2009 -- LL to adjust.

4 _____ 09-09-02

4 _____ 09/09/04 (4)

0969108 
CMF 09-09-08.